

G	G1	d _{max}	M _{min}	L _{min}	H	FACES
1/4	1/8	8,0	4,0	10,5	14,0	6
3/8	1/5	11,5	5,0	11,0	18,0	6
	1/4	11,5	5,0	11,0	18,0	6
1/2	1/8	15,0	5,0	14,5	22,0	6
	1/4	15,0	5,0	14,5	22,0	6
	3/8	15,0	5,0	14,5	22,0	6
3/4	1/4	20,5	5,5	15,5	27,5	6
	3/8	20,5	5,5	15,5	27,5	6
	1/2	20,5	5,5	15,5	27,5	6
1	3/8	26,0	6,0	18,0	34,5	6
	1/2	26,0	6,0	18,0	34,5	6
	3/4	26,0	6,0	18,0	34,5	6
1 1/4	1/2	34,5	6,5	20,5	43,0	6
	3/4	34,5	6,5	20,5	43,0	6
	1	34,5	6,5	20,5	43,0	6
1 1/2	1/2	40,0	6,5	20,5	49,0	6
	3/4	40,0	6,5	20,5	49,0	6
	1	40,0	6,5	20,5	49,0	6
	1 1/4	40,0	6,5	20,5	49,0	6
2	1	51,0	7,0	25,0	61,0	6
	1 1/4	51,0	7,0	25,0	61,0	6
	1 1/2	51,0	7,0	25,0	61,0	6
2 1/2	1 1/2	65,5	7,0	27,0	76,0	8
	2	65,5	7,0	27,0	76,0	8
3	2	77,5	7,5	30,0	90,0	8
	2 1/2	77,5	7,5	30,0	90,0	8

